

1B

	L #	Hits	Search Text	DBs	Time Stamp
1	L1	9419	((427/8,9,10,142,404,405,419.2,524) or (204/192.15,192.6)).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
2	L2	51431	Eddy adj current	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
3	L3	143	L2 with (thick\$7 depth height microns micrometer ".mu." ".mu.m") with (oxide oxidat\$5 oxidiz\$7 corrod\$5 corrosion sulfidiz\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:51
4	L4	317	L2 same ((thick\$7 depth height microns micrometer ".mu." ".mu.m") with (oxide oxidat\$5 oxidiz\$7 corrod\$5 corrosion sulfidiz\$5))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
5	L5	3523	L2 with (turbine rotor blade vane superalloy carbide near2 alloy)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
6	L6	5231	L2 same (turbine rotor blade vane superalloy carbide near2 alloy)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
7	L7	3	L3 same L5	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46

Draws
Search
↓

2B

	L #	Hits	Search Text	DBs	Time Stamp
8	L8	12	(L3 and L5) not L7	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
9	L9	1	(L3 same L6) not (L7 or L8)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
10	L10	4	(L4 same L5) not (L7 or L8 or L9)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
11	L11	5	(L4 same L6) not (L7 or L8 or L9 or L10)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
12	L12	10	(L4 and L6) not (L7 or L8 or L9 or L10 or L11)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
13	L13	6	((L3 or L5) and L1) not (L7 or L8 or L9 or L10 or L11 or L12)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
14	L14	2	((L4 or L6) and L1) not (L7 or L8 or L9 or L10 or L11 or L12 or L13)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46

3B

	L #	Hits	Search Text	DBs	Time Stamp
15	L15	6	(L3 and (turbine rotor blade vane superalloy carbide near2 alloy)) not (L7 or L8 or L9 or L10 or L11 or L12 or L13 or L14)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
16	L16	24	(L4 and (turbine rotor blade vane superalloy carbide near2 alloy)) not (L7 or L8 or L9 or L10 or L11 or L12 or L13 or L14 or L15)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
17	L17	6	(L4 same (cast casting mold molding)) not (L7 or L8 or L9 or L10 or L11 or L12 or L13 or L14 or L15 or L16)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:48
18	L18	99	(L2 and (cast casting mold molding) and turbine and repair\$7) not (L7 or L8 or L9 or L10 or L11 or L12 or L13 or L14 or L15 or L16 or L17)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:50
19	L19	0	L18 and ((thick\$7 depth height microns micrometer ".mu." ".mu.m") with (oxide oxidat\$5 oxidiz\$7 corrod\$5 corrosion sulfidiz\$5) same (cast casting mold molding))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:53
20	L20	42	L18 and ((thick\$7 depth height microns micrometer ".mu." ".mu.m") with (oxide oxidat\$5 oxidiz\$7 corrod\$5 corrosion sulfidiz\$5))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:54
21	L21	42	L20 and (gas adj turbine)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:55

↓
L23
↓
L24

4B,

	L #	Hits	Search Text	DBs	Time Stamp
22	L22	0	L21 and (superalloy MCrAlY)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:56
23	L23	42	L21 and (Ni nickel Co cobalt Carbide near2 alloy)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:57
24	L24	37	L23 and (frequency HF LF) ? all useless	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:58
25	L25	0	L24 not L23	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:59
26	L26	5	L23 not L24 useless	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:59

L28 "Co.m/c" ~~no other~~ ~~hits~~ (37)

deletes these only

L28 (57) L18 not L20

4B₂

	L #	Hits	Search Text	DBs	Time Stamp
22	L22	0	L21 and (superalloy MCrAlY)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:08
23	L23	42	L21 and (Ni nickel Co cobalt Carbide near2 alloy)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:09
24	L25	0	L24 not L23	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:59
25	L24	37	L23 and (frequency HF LF)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:10
26	L26	5	L23 not L24	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:05
27	L27	37	L21 and (Ni nickel "Co.m/c." cobalt Carbide near2 alloy)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:09
28	L28	57	L18 not L20	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:08

↓

	L #	Hits	Search Text	DBs	Time Stamp
29	L29	10	L28 and (superalloy MCrAlY)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:08
30	L30	23	L28 and (Ni nickel "Co.m/c." cobalt Carbide near2 alloy)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:09
31	L31	24	L29 or L30	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:09
32	L32	19	L31 and (frequency HF LF)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:11
33	L33	5	L31 not L32	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:17
34	L34	43840	(L2 measur\$7 test\$5 monitor\$5) same ((thick\$7 depth height microns micrometer ".mu." ".mu.m") same (oxide oxidat\$5 oxidiz\$7 corrod\$5 corrosion sulfidiz\$5))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:26
35	L35	134	(L2 and L34 and (gas adj turbine)) L38 L35 NOT --- all other parts search	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:27

	L #	Hits	Search Text	DBs	Time Stamp
36	L36	0	(L35 and (cast casting mold molding) same (turbine repair\$7)) not (L7 or L8 or L9 or L10 or L11 or L12 or L13 or L14 or L15 or L16 or L17 or L31 or L23)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:30
37	L37	0	(L35 and (cast casting mold molding) same (turbine blade vane rotor superalloy repair\$7Ni nickel "Co.m/c." cobalt Carbide near2 alloy)) not (L7 or L8 or L9 or L10 or L11 or L12 or L13 or L14 or L15 or L16 or L17 or L31 or L23)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:31

5B

	L #	Hits	Search Text	DBs	Time Stamp
29	L29	(10)	L28 and (superalloy MCrAlY)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:08
30	L30	(23)	L28 and (Ni nickel "Co.m/c." cobalt Carbide near2 alloy)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:09
31	L31	(24)	L29 or L30	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:09
32	L32	(19)	L31 and (frequency HF LF)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:10
33	L33	(5)	L31 not L32	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:10